

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

MI# 196 810609

MIS-000-001-188

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name BASF Wyandotte Corporation
Street P. O. Box 181
City Parsippany, State N.J. Zip Code 07054

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Riverview
Street Jefferson Avenue
City Riverview County Wayne State MI Zip Code 48192

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Gebrian, John, Manager Corporate
Phone (201) 263-5674 Environmental
Protection

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1951 To (Year) 1979

E Waste Type:

During 1971, 16,000 tons of material containing approximately 1% arsenic (D004) were stored on the site which was leased to Chem-Met Service Inc. The storage was with permission of the Michigan DNR and the material was subsequently removed by Chem-Met.

There are reports, which could not be substantiated, that some wastes from the plant in the North Works were brought to the Riverview property.

Surveys conducted pursuant to the sale of the property indicate the minor presence of some hazardous chemicals.

The nature and sale of the property is currently the subject of a litigation between the parties of the sale and the State of Michigan and the U. S. EPA.

EPA Region 5 Records Ctr.



382448

000530 JUN -9 81

SEE subsequent ATTACHED
(E.) WASTE TYPE

JUN 12 1981

Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☒ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet _____

gallons _____

Total Facility Area

square feet _____

acres 30 *A***G Known, Suspected or Likely Releases to the Environment:**

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ None

Unknown

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required

Dunn, R. E., Secretary of

Name BASF Wyandotte CorporationStreet P.O. Box 181City ParsippanyState N.J. Zip Code 07054Signature *R. E. Dunn*Date 6/5/81

- ☐ Owner, Present
☒ Owner, Past
☐ Transporter
☐ Operator, Present
☒ Operator, Past
☐ Other

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

Subsequent
This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

810702
Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

MIS-000-001-188

DUPLICATE NO.

MIS-000-001-188

MIS-000-001-272

Mi # 286

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name BASF Wyandotte Corporation
Street P. O. Box 181
City Parsippany, State N.J. Zip Code 07054

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Riverview
Street Jefferson Avenue
City Riverview County Wayne State MI Zip Code 48192

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Gebrian, John, Manager Corporate Environmental Protection
Phone (201) 263-5674

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1951 To (Year) 1979

E Waste Type

ENTER
During 1971, 16,000 tons of material containing approximately 1% of mono sodium methane arsonate herbicide (D004) were stored on the site which was leased to Chem-Met Service Inc. The storage was with permission of the Michigan DNR and the material was subsequently removed by Chem-Met.

There are reports, which could not be substantiated, that some wastes from the plant in the North Works were brought to the Riverview property.

Surveys conducted pursuant to the sale of the property indicate the minor presence of some hazardous chemicals.

The nature and sale of the property is currently the subject of a litigation between the parties of the sale and the State of Michigan and the U. S. EPA.

000005 JUL -281

JUL 02 1981

Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet _____

gallons _____

Total Facility Area

square feet _____

acres 30 _____

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ None

Unknown _____

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify, check "Other".

Name Dunn, R. E., Secretary of
BASF Wyandotte Corporation

Street P.O. Box 181

City Parsippany State N.J. Zip Code 07054

Signature R. E. Dunn

Date 6/25/81

- ☐ Owner, Present
☒ Owner, Past
☐ Transporter
☐ Operator, Present
☒ Operator, Past
☐ Other

BASF Wyandotte Corporation



100 Cherry Hill Road
P.O. Box 181
Parsippany, N.J. 07054
201/263-5280

June 26, 1981

Keith Fry
Director
Corporate Environmental Protection

U.S. Environmental Protection Agency
Region V
Sites Notification
Chicago, Illinois 60604

Certified Mail
P29 2144642

Gentlemen:

BASF Wyandotte Corporation (BWC) is submitting an amended Notification of Hazardous Waste Site previously submitted on June 9, 1981. This enclosed document should replace that submitted on June 9, 1981.

The word, "arsenic", in the first sentence of Section E (waste type) is replaced with the proper chemical name, "mono sodium methane arsenate herbicide", which properly reflects the actual nature of the material stored on the site.

If there are any questions, please contact me.

Very truly yours,

BASF WYANDOTTE CORPORATION

A handwritten signature in cursive script that reads "Keith Fry".
Keith Fry

KF:ff
Attachment

JUL 02 1981

BASF Wyandotte Corporation



100 Cherry Hill Road
P.O. Box 181
Parsippany, N.J. 07054
201/263-0200

Certified Mail
P29 2144633

June 5, 1981

U. S. EPA Region 5
Sites Notification
Chicago, Ill 60604

Gentlemen:

Enclosed are the submissions of hazardous waste sites as required by Section 103(c) of the Comprehensive Environmental Response, Compensation and Liability Act of 1980.

BASF Wyandotte Corporation owns and operates the following;

Holland, Michigan
Wyandotte, Michigan

BASF Wyandotte Corporation formerly owned and operated the following;

Riverview, Michigan
Port Edwards, Wisconsin

Very truly yours,

Keith Fry
Keith Fry, Director
Corporate Environmental
Protection

KF:if
enclosures

JUN 12 1981



BASF Wyandotte Corporation
100 Cherry Hill Road
P.O. Box 181
Parsippany, N.J. 07054



US EPA Region 5
Sites Notification
Chicago, ILL 60604

RETURN RECEIPT
REQUESTED

